

## BLUETOOTH

### Change of index on the Blue PUCK T EN12830

#### 1. MAIN FEATURE & REASON FOR PRODUCT CHANGE:

Change of index on Blue PUCK T EN12830 to be in correlation with the indexes of the Bluetooth and casing range of product. No HW or FW change.

#### 2. IDENTIFICATION

This new index is identified: **IDF25251x** instead IDF30241x

#### 3. AFFECTED PRODUCTS

| <i>PRODUCT<br/>END OF LIFE NAME</i> | <i>PRODUCT<br/>PREVIOUS<br/>REFERENCE</i> | <i>NEW PRODUCT<br/>REFERENCE</i> | <i>REMARKS</i>        |
|-------------------------------------|---|----------------------------------|-----------------------|
| <b>STANDARD BLE RANGE</b>           |   |                                  |                       |
| Blue PUCK T EN12830                 | IDF30241D                                 | <b>IDF25251D</b>                 | V300 firmware version |
| Blue PUCK T EN12830                 | IDF30241E                                 | <b>IDF25251E</b>                 | V400 firmware version |

#### 4. SCHEDULE

**This modification has immediate effect. Any order placed with the old index will be modified and will be the subject of an order acknowledgment with the new index.**

Montpellier, January, 07<sup>th</sup>, 2022

Pierre BONZOM  
CEO

